



PS 7

Ø -0,3 0,3-0,5 0,5-0,9 0,9-1,5 1,5-3,0 3,0-5,0 5,0-7,0 7,0-9,0 9,0-15,0

TYPE PS 7-0,3 PS 7-0,5 PS 7-0,9 PS 7-1,5 PS 7-3,0 PS 7-5,0 PS 7-7,0 PS 7-9,0 PS 7-15,0

A	51,5	52	91	119	145	180	227	227	384
B	50	50	86	110	133	168	215	215	360
C	14,5	16,5	29,5	36,5	49	52	65	68	86
D	4	7	17	23	31	40	52	62	80
E	4	4	6	7	10	9	12,5	12,5	25
F	40	54	88	148	159,5	207	375	375	610
G	11	11	16	20	23	23	30	30	40
H	20	20	35	45	55	70	90	90	150
K	20	20	49	65	80	100	135	135	210
L	48	62	100	162	179,5	225	400	400	660
M	3,5	3,5	5,5	6,6	6,6	9	9	9	17
N	12	13	22	27	36	36	47,3	45,8	58,5
O			21	25	30	40	45	45	90
P	56	70	112	178	195,5	245	424	424	690
R	40	40	60	95	120	160	200	200	300
kg	0,3	0,4	1,5	3,6	5,6	8,7	19,9	21,8	82
WR	4	7	17	23	31	40	520	62	800
F [N]	7	13	25	59	353	569	951	1374	1760